

Spiral kneader mod.50C-F

This exploded view diagram illustrates the assembly of the Spiral kneader mod.50C-F. The components are numbered 1 through 68, indicating the sequence of assembly. The diagram shows the main body (1), the spiral kneader (2), the motor (21), and the drive shaft (20). Key components include the motor (21), drive shaft (20), gears (12, 17, 31, 38), bearings (13, 18, 19, 32, 36), and the spiral kneader (2). The diagram also shows the base (16) and the wheels (26). A callout box labeled 'A' shows a screwdriver (59) being used to tighten a screw (58) into the base. The diagram is a technical drawing with clear lines and numbers, suitable for a manual.

IMPASTATRICE A SPIRALE MOD.IM50C-F

SPIRAL KNEADER MOD.IM50C-F

| Rif No | Codice Code | Caratteristiche Characteristics | Descrizione Description | |
|--------|-------------|---------------------------------|-------------------------|-------------------------|
| 1 | SL2657 | | Coperchio | Cover |
| 2 | SL2727 | | Perno | Pivot |
| 3 | SL2740 | 5/8"x3/8" | Catena | Chain |
| 4 | SL2729 | | A bero | Shaft |
| 5 | SL2736 | 6008 2RS | Cuscinetto | Bearing |
| 6 | SL0233 | 6205 2RS | Cuscinetto | Bearing |
| 7 | SL2724 | | Supporto | Support |
| 8 | SL0035 | | Battuta | Stop |
| 9 | SL0036 | | Camma | Cam |
| 10 | SL0885 | | Microinterruttore | Microswitch |
| 11 | SL0397 | | Staffa | Bracket |
| 12 | SL2734 | 5/8"x3/8" Z=24 | Pignone | Pinion |
| 13 | SL2647 | UCF206 | Supporto | Support |
| 14 | SL2722 | | Staffa | Bracket |
| 15 | SL0934 | 400V/3Ph/50Hz | Impianto elettrico | Electric installation |
| 16 | SL2830 | | Coperchio | Cover |
| 17 | SL2645 | 3/8"x7/32" Z=20 | Pignone | Pinion |
| 18 | SL0047 | 8x11 | Linguetta | Key |
| 19 | SL2671 | 10x16 | Linguetta | Key |
| 20 | SL2840 | | A bero | Shaft |
| 21 | SL2642 | | Riduttore | Gear box |
| 22 | SL2643 | 400V/3Ph/50Hz | Motore | Motor |
| 22 | SL2718 | 400V/3Ph/50Hz (2 speed) | Motore | Motor |
| 23 | SL1668 | PG11 | Pressacavo | Cable clamp |
| 24 | SL1841 | 3Ph+Gnd | Cavo elettrico | Electric cable |
| 25 | SL0052 | | Piedino | Foot |
| 26 | SL2829 | | Base | Base |
| 27 | SL0937 | | Scatola | Box |
| 28 | SL0396 | | Guarnizione | Gasket |
| 29 | SL0807 | Stop | Pulsante | Push button |
| 30 | SL1049 | Start | Pulsante | Push button |
| 31 | SL2646 | 3/8"x7/32" Z=110 | Corona | Crown |
| 32 | SL2741 | 3/8"x7/32" | Catena | Chain |
| 33 | SL2726 | | Asta | Rod |
| 34 | SL2728 | | A bero | Shaft |
| 35 | SL2735 | 6206 2RS | Cuscinetto | Bearing |
| 36 | SL2723 | | Supporto | Support |
| 37 | SL2588 | 51206 | Cuscinetto | Bearing |
| 38 | SL1616 | ø25 | Seeger | Seeger |
| 39 | SL1369 | | Spirale | Spiral |
| 40 | SL2875 | | Protezione | Protection |
| 41 | SL2711 | | Coperchio | Cover |
| 42 | SA1190 | (50C) Assembly | Pentola | Pan |
| 42 | SL1304 | (50F) | Pentola | Pan |
| 43 | SL2733 | 5/8"x3/8" Z=15 | Pignone | Pinion |
| 44 | SL2725 | | Flangia | Flange |
| 45 | SL1090 | | Distanziale | Spacer |
| 46 | SL1629 | 3/8"x7/32" | Giunto | Joint |
| 47 | SL2780 | 8x7x25 | Linguetta | Key |
| 48 | SL2776 | 5/8"x3/8" | Giunto | Joint |
| 49 | SL2655 | | Ruota | Wheel |
| 50 | CAVIMPF30BR | | Carrello | Trolley |
| 51 | SA1700 | Assembly | Supporto | Support |
| 52 | SA1600 | Assembly | Supporto | Support |
| 53 | SL2743 | 2 speed | Commutatore di velocità | Speed changeover switch |
| 54 | SL1334 | (50C) | Guarnizione | Gasket |
| 55 | SL1303 | (50C) | Flangia | Flange |
| 56 | SL2839 | (50C) | Flangia | Flange |
| 56 | SL2868 | (50F) | Flangia | Flange |
| 57 | SL1302 | (50C) | Flangia | Flange |
| 58 | SL1932 | (50C) | Perno | Pivot |
| 59 | SL2843 | | Molla | Spring |
| 60 | SL2831 | | Giunto | Joint |
| 61 | SL2832 | | A bero | Shaft |
| 62 | SL2672 | ø30 | Seeger | Seeger |
| 63 | SL2834 | | Testata | Head |
| 64 | SL2837 | | Coperchio | Cover |
| 65 | SL2838 | | Supporto | Support |
| 66 | SL2841 | | Leva | Lever |
| 67 | SL2842 | | Perno | Pivot |
| 68 | SA1100 | Assembly | Supporto | Support |

(*): fuori produzione / out of production